

DP 500/510 -


Mobile dew point meters with data logger

Applications:

- Compressed air: Examination of refrigeration, membrane, adsorption dryers
- Technical gases: Residual moisture measurement in gases such as N2, O2 etc.
- Plastics industry: Examination of granulate dryers

Special features:

- Precise dew point measurement down to -112 °F
- · Quick response time
- 3.5" graphic display / easy operation via touch screen
- Integrated data logger for storage of the measured values
- USB interface for reading out via USB stick
- Calculates all necessary moisture parameters like g/m³, mg/m³, ppm, V/V, g/kg, Ctd, atm
- 2nd freely assignable sensor input for third-party sensors (only DP 510)
- International: up to 8 languages selectable





Quick installation by means of measuring chamber and quick coupling




Ideal for service technicians-all-in-one case



Dry container - for sensor protection and quick adaption time





Everything at a glance



Measurement curves are displayed graphically, so the operator sees at a glance the behavior of the dryer since the start of the measurement.



All physical parameters of the humidity measurement are calculated automatically. The DP 510 also displays the measured values of the external sensor.



Up to 100 million measured values can be stored. Each measurement can be stored with a comment, e.g. measuring site name.

The time interval can be freely set.

DESCRIPTION	ORDER NO.
Set DP 500 in a case - consisting of:	0600 0500
- Portable dew point meter DP 500 for compressed air and gases	0560 0500
- Mobile measuring chamber up to 232 psi	0699 4490
- Diffusion-tight PTFE hose with quick coupling, length 3.2 ft.	0554 0003
- Power supply for DP 500/DP 510	0554 0009
- Control and calibration set 11.3% RH	0554 0002
- Quick-lock coupling	0530 1101
- Dry container for CS dew point sensors	0699 2500
- Transportation case (small) for DP 500	0554 6500
Set DP 510 in a case - consisting of:	0600 0510
- Mobile dew point meter DP 510 with one additional input for external sensors	0560 0510
- Mobile measuring chamber up to 232 psi	0699 4490



DESCRIPTION	ORDER NO.
- Diffusion-tight PTFE hose with quick coupling, length 40 inch	0554 0003
- Power supply for DP 500/DP 510	0554 0009
- Control and calibration set 11.3% RH	0554 0002
- Quick-lock coupling	0530 1101
- Dry container for CS dew point sensors	0699 2500
- Transportation case (large) for DP 510 as well as other sensors	0554 6510
Furter options, not included in the set:	
Option: "Mathematics calculation function" for 4 freely selectable channels, (virtual channels): addition, subtraction, division, multiplication	Z500 5107
Option: "Totalizer function for analog signals"	Z500 5106
CS Basic – data evaluation graphically and in table form - reading of the measured data via USB or Ethernet, licence for 2 workstations	0554 8040
Precision calibration at -40 °F37.40 °F with ISO certificate	0699 3396
Additional calibration point freely selectable in the range between-11268 °F	0700 7710
High pressure measuring chamber up to 5076 psi	0699 3590
Measuring chamber for atmospheric dew point	0699 3690
Measuring chamber for granulate dryers with minimum overpressure	0699 3490
Portable dew point meter DP 510 for compressed air and gases (high pressure version up to 5076 psi)	0560 0512
Portable dew point meter DP 500 for compressed air and gases (high pressure version up to 5076 psi)	0560 0501



TECHNICAL DATA DP 500/510		
Display:	3.5" touch screen	
Measuring range:	112122 °F -4158 °F 0100% RH	
Accuracy:	± 0.5 °Ftd. at 14122 °F Typ. ± 2 °Ftd (further range)	
Moisture parameters:	lb/CF, mg/m³, ppm V/V, g/kg, °Ftd atm, % RH	
Pressure range:	-1725 psi standard -15076 psi special version	
Interface:	USB interface	
Data logger:	16 GB SD memory card (100 million values)	
Power supply:	Output voltage: 24 VDC ± 10% Output current: 120 mA in continuous operation	
Power supply:	Internal rechargeable Li-lon batteries, approx. 12 h continuous operation, 4 h charging time	
Screw-in thread:	NPT 1/2" or G 1/2" stainless steel	
Ambient temperature:	14122 °F	
EMC:	DIN EN 61326-1	



Camera key saves current screen as an image file. No additional software necessary.